PRINTED: 01/05/2017 FORM APPROVED

_	Division	vision of Health Service Regulation					ALLKO VED	
	STATEMEN	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:	(XX) MULTIPI A. BUILDING	E CONSTRUCTION	(XS) DATE COMP		
_	**		HAL045115	B. WING		R 12/1	3/2016	
l	NAME OF PROVIDER OR SUPPLIER STREET ADD			DRESS, CITY, STATE, ZIP CODE				
L	CHERRY	HERRY SPRINGS VILLAGE 358 CLEAR CREEK ROAD HENDERSONVILLE, NC 28792						
	(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPRIED TO THE	D BE COMPLETE		
	(C 000)	Initial Comments		(C 000)	-			
		Report of Follow-up 12-13-2016.	Survey by Dennis Harrell on					
		Not all deficiencies action is required.	were corrected. Further					
	(C 189)	Building Equipment	Maintained Safe, Operating	(C 189)				
		SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.						
Display	vision of He	are prevented from are not fitting prope and smoke. Corrick completely and latel fire that begins in or to the corridor and the Findings still include b. Corridor door the	ration, many corridor doors closing quickly and latching or rly to resist the passage of fire or doors that do not close in present the possibility that a ne space can quickly spread the remainder of the facility,		1.b. Corridor door to the Litchen has had vepair and shim placed to make door fit I close Completely		47/17	
ABORATORADIRECTOR'S OR PROVIDER/GUPPLIER REPRESENTATIVE'S SIGNATURE TITLE - XXX DATE								
clary Hamelton Executive Dietor /13/17								
2 1	6GUR22 If continuation wheet 1 of 1							